Notebook, N-05-01-03

05-01-03

Original cells in Sec. I. —

4060 A, B + C
D, E + F.
4061 A, B + C.
4110, 11
4197, 98, 99
4203, 11, 13
4264, 65, 66
4354, 55, 56
4285, 86, 87
4289, 90, 91
4294, 95, 96
4114, 05, 06
4141, 18, 19
4141, 20, 24
4144, 25, 26
4158, 59, 61
4162, 64, 65.
4165, 69, 70.
4178, 81, 82.

4529, 30, 31,
4534, 35, 34,
4597, 98, 99, K
4590, 91, 92, K
4594, 95, 96
4601, 02
4634, 35, 37
4631, 32, 33
4634, 36, 39
4660, 61, 64
4665, 66, 67, 68,
4670, 71, 72.
4699, 99, 4700.
4723, 23, 24.
4732, 33, 34.
4766, 66, 67.
4775, 76, 77.
Also [illegible] 1-40 [illegible]

Section I.

Small Cell Interconnect Test.

40 groups of 3 cells each.

Started January 3, 1905 at 3.00 A.M.

Cells [illegible] @ 3.00 amps. on starting, then 4 hrs. during @ .100 amps.

7 hours @ 4 hrs. @ .200 amps. — during 4 hrs. @ .100 amps.

Changes come at 4.00, 8.00, 12 [illegible] A.M.

Must be looked at for [illegible] of short circuit and tested for short circuits every morning.

Changes must be O.K'd by the day night man, and test of short circuits notified by the day man each day.

Any irregularities or deviations from the regular order of working must be recorded in this book.

1/3/05.

January 3, 1905.
Tests O.K. – W.E.N.
1 Changes O.K. – W.E.N.
1st am – 12 hrs duty

January 4.
Night changes O.K. – C.A.S.
4 Tests O.K. – A.K.
Day changes O.K – A.K.

January 5
Night changes O.K., C.A.S.
7 Tests O.K. – W.E.N.
Day changes O.K. except unit on duty
7 minutes late at 4.00 P.M. – W.E.N.

January 6
Night changes O.K. C.A.S.
10 Solution test O.K. – no S.C. Test – W.E.N.
Day changes O.K. – W.E.N.

January 7
Night changes O.K C.A.S.
13 Tests O.K. – W.E.N.
Day changes ok ABS.

January 9th 1905
Night changes O.K. C.A.S.
16 off charge 10 minutes – ABS.
Tests O.K. ABS.
Day changes O.K ABS

January 9th
Night changes O.K. C.A.S.
19 Tests O.K. A.K.
Day changes O.K. A.K.

January 10th
Night changes O.K. C.A.S.
22 Off charge 30 minutes 1.15 to 1.35 A.M.
Off N 740 ABS.
Tests OK – A.K.
Day changes OK ABS.

January 11th
Night changes O.K C.A.S.
25 Tests O.K A.K.
Day changes O.K. A.K + ABS.

January 12
Night changes O.K C.A.S.
28 Tests OK ABS.
Day changes OK ABS

January 13th 1905
Night Changes O.K. C.A.S.
31 Tests O.K. A.K.
Day changes O.K. A.K.
Off charge 10 min ABS

January 14 - 1905
Night changes O.K. C.A.S.
34 Off Quarters 10 Minutes to complete
Tests O.K. A.K.
Day changes O.K. A.K.

January 15
Night Changes O.K. C.A.S.
37 Tests O.K. A.K.
Day changes O.K. A.K.

January 16
Night Changes O.K. C.A.S.
Tests O.K. A.K.
40 Day changes O.K. ABS A.K.

January 17
Night Changes O.K. C.A.S.
43 Tests O.K. A.K.
Day changes O.K. A.K.

January 18
46 Night Changes O.K. C.A.S.
Tests O.K. A.K.
Day changes O.K. A.K.

January 19
49 Night Changes O.K. C.A.S.
Tests O.K. A.K.
Day changes O.K. A.K.

January 20-05
52 Night Changes O.K. C.A.S.
Tests O.K. A.K.
Day changes O.K. ABS A.K.

January 20th 1905
Off at midnight to stand
until 4 o P.M. 1-21-05 for a
regular change and run on
board with readings.
53

January 23rd 1905
Day Changes OK-
Tests OK -
Night Changes OK- C.A.S.
1½ hrs Rum 12 hrs Chg —
5.4 1 run ends
Took off at 8.00 P.M. after one
6.0 12 hr. chg + 4 hr. disch'g. to run
again on board - W.E.H.

January 27, 1905.
0. On for 12 hr. chg @ 4.00 P.M.
Tests O.K. - W.E.H.

January 28-
Night Changes OK. C.A.S.
3 Test O.K. W & P
Day Changes OK W. E. H.

January 29
Night changes OK. C.A.S.
4 S.C. Test O.K. - W.E.H.
Day changes O.K. - W.E.H.

Av. charge 320 amps. Disch'g - 400

January 30 - 1905
Night Changes OK. C.A.S.
9 S.C. Test O.K. - W.E.H.
Solution Test O.K. - W & P
Day changes O.K. - W & P

January 31 -
Night Changes OK - C.A.S.
12 Tests O.K. Sp. Gravity - W.E.H.
Day changes O.K. - W.E.H.

February 1st - 05
Night Changes OK. C.A.S.
15 Tests OK - A&Co
Day Changes OK A&Co

February 2nd
Night Changes OK. C.A.S.
2 Tests OK. Smith
Day changes O.K. Smith

February 3rd
Night Changes OK. C.A.S.
~ Tests O.K. Smith
Day changes OK. Smith